Table 3. Historic Resources Survey Phase 1, Nevadaville, Colorado

Photograph	Site ID # NHL ID #	Address	Historic Name Est. construction date	NHL District contrib	NR eligible	Local eligible	Integrity Existing Conditions Comments	Historic photograph
	5GL.7.332 N-1	400 Nevadaville Rd.	Nevadaville Building #1	Yes/Yes	Yes B, C	Yes	Date of side additions are unknown, but the large, central stone portion retains a high degree of integrity	
	5GL.7.335 N-14	1069 Nevadaville Rd.	Gest House Nevadaville Building #14	Yes/Yes	Yes A, B	Yes Listed	New siding is similar to the historic siding, and does not negatively impact this building's integrity.	
	5GL.7.336 N-27	1071 Nevadaville Rd.	Rice-Andrews-Paul House Nevadaville Building #27	Yes/Yes	Yes A, C	Yes	Alterations include a shed roof dormer, new doors and windows, and a small frame addition on the side. These do not detract from the building's overall integrity.	
	5GL.7.337 N-35	1189 Nevadaville Rd.	Richards-James House Nevadaville Building #35	Yes/Yes	Yes C	Yes	The wood clapboard siding is likely still extant beneath the rolled asphalt covering, which was likely added in the latter half of the 20th century. The building retains enough integrity for individual listing.	

Photograph	Site ID # NHL ID #	Address	Historic Name Est. construction date	NHL District contrib	NR eligible	Local eligible	Integrity Existing Conditions Comments	Historic photograph
	5GL.7.338 N-34	1109 Nevadaville Rd.	Valentine Devinney House Devinney-Mansur-Prouse House Mary Nicholas House William Russell, Jr. House Nevadaville Building #34	Yes/Yes	Yes C	Yes	Changes to the small north shed addition do not detract from the building's overall historic appearance.	
	5GL.7.339 N-38	[no address]	Davis Duncan Cabin Nevadaville Building #38	Yes/Yes	No	Yes	The loss of the east wing (now replaced with a metal shed wing) impacts this building's individual eligibility status.	
	5GL.7.340 N-50	1091 Nevadaville Rd.	Nannie Reseigh House Nevadaville Building #50	Yes/Yes	Yes C	Yes Listed	This house retains a very high degree of integrity, and would be individually eligible.	
	5GL.7.341 N-52	1099 Nevadaville Rd.	Phillip B. Hicks House Maddern-Johns House Bill Boone House Nevadaville Building #52	Yes/Yes	Yes C	Yes	Although in deteriorated condition in the rear, this building still retains enough integrity for individual listing.	

Photograph	Site ID # NHL ID #	Address	Historic Name Est. construction date	NHL District contrib	NR eligible	Local eligible	Integrity Existing Conditions Comments	Historic photograph
	5GL.7.342 N-66	1087 Nevadaville	Alvin Church House Jane Williams House Nevadaville Building #66	Yes/Yes	Yes C	Yes	Despite siding and door changes, this building still retains its historic appearance.	
	5GL.7.343 N-72	1072 Nevadaville Rd.	Nevadaville Building #72	Yes/Yes	Needs Data	Yes	This building has been altered multiple times over the years. More data (additional historic photographs) may be needed to determine individual eligibility to the N.R.	
	5GL.7.344 N-75	1081 Nevadaville Rd.	Bennetts House John Davey House Nevadaville Building #75	Yes/Yes	No	Yes	This building has gained and lost several additions over the years. Siding, window and door changes also impact its individual eligibility.	
	5GL.7.345 N-93	1263 Nevadaville Rd.	Ellis House Quick House Furze House Edith James House Nevadaville Building #40	Yes/Yes	No	Yes	Siding and door changes impact this building's individual eligibility, although it still contributes to the NHL district.	

Photograph	Site ID # NHL ID #	Address	Historic Name Est. construction date	NHL District contrib	NR eligible	Local eligible	Integrity Existing Conditions Comments	Historic photograph
	5GL.7.346 N-6	999 Nevadaville Rd.	Rachofsky Dry Goods Store Nevadaville Building #6	Yes/No	No	Needs data	1970s storefront and 2nd story façade infill, and loss of 2nd store on the rear, negatively impacts integrity and thus its eligibility as a contributing building to either the N.R. or N.H.L. district	
	5GL.7.347 N-10	1039 Nevadaville Rd.	Kramer's Saloon Nevadaville Building #10	Yes/Yes	Yes A, C	Yes	This commercial building retains a high degree of integrity and would be individually eligible for the N.R.	
	5GL.7.348 N-16	Main Street [no building #]	Bon Ton Saloon Nevadaville Building #16	Yes/Yes	Yes A, C	Yes	This brick saloon retains a high degree of integrity and would be individually eligible for the N.R.	
	5GL.7.349 N-40-N	1263 Nevadaville Rd.	Norman Palo House Pinky's Palace Nevadaville Building #93	No/No	No	No	This building was not constructed during the historic period, and would not be eligible either as a contributing building or individually.	

Photograph	Site ID # NHL ID #	Address	Historic Name Est. construction date	NHL District contrib	NR eligible	Local eligible	Integrity Existing Conditions Comments	Historic photograph
	5GL.7.350 N-18	1040 Nevadaville Rd.	Nevadaville City Hall Nevadaville Building #18	Yes/Yes	Yes A, C	Yes	Despite loss of the bell tower and asphalt siding over the historic clapboard siding, this building still retains enough integrity to be individually eligible for the N.R.	
	5GL.7.351 N-11	1043 Nevadaville Rd.	Nevadaville Masonic Block Building; Nevada Lodge No. 4 A.F. & A.M. Nevadaville Building #11	Yes/Yes	Yes A, C	Yes Listed	This building retains a high degree of integrity both on the interior and exterior, although the windows were replaced after vandals destroyed the historic windows.	

Note: As all of the extant properties in Nevadaville had a privy at one time, they may also be eligible under Criterion D for non-aboriginal historical archaeology if the remains of a privy are found. Any site work or excavations should take into account this possibility.